



GAIL FARBER, Director

COUNTY OF LOS ANGELES

DEPARTMENT OF PUBLIC WORKS

"To Enrich Lives Through Effective and Caring Service"

BUILDING AND SAFETY DIVISION
PROPERTY REHABILITATION SECTION
SAN GABRIEL OFFICE
125 S. BALDWIN AVE.
ARCADIA, CALIFORNIA 91007
Telephone: 626-574-0941
Fax: 626-446-4425
<http://www.ladpw.org>

ADDRESS ALL CORRESPONDENCE TO:
125 S. BALDWIN AVE.
ARCADIA, CALIFORNIA 91007

IN REPLY PLEASE
REFER TO FILE:

INFORMAL NOTICE SUBSTANDARD CONDITIONS

March 3, 2009

Rodriguez, Victoria
2366 Glenrose Ave
Altadena, CA 91001-0000

Property Address: **2366 GLENROSE AV, ALTADENA**
AIN: **5835-017-014**

The following substandard property or substandard building(s) or both were observed on this property:

- Broken windows and doors.
- Attractive nuisances dangerous to children, i.e., abandoned or broken equipment, neglected machinery, refrigerator(s), and freezer(s).
- Broken or discarded household furniture or household equipment or both in yard areas for unreasonable periods.
- Miscellaneous articles of personal property about the premises.
- Trash, junk, and debris about the premises.
- Abandoned, wrecked, dismantled, or inoperative motor vehicles (LISTED BELOW) or parts thereof stored for unreasonable periods on the premises.

This "INFORMAL NOTICE" is provided to allow you to abate (correct) the noted substandard conditions by **March 18, 2009**. When you **have abated** (corrected) the substandard conditions, please contact your inspector so the work done may be inspected and the Code enforcement action closed by the deadline date.

If the substandard conditions are **not abated**, the Department of Public Works will initiate formal Code enforcement action and you will receive a bill in the amount of **\$429.50** for the County's cost to conduct investigation and processing. If the bill is not paid, all of this agency's actual cost, plus an additional **\$207.80**, shall be placed as a special assessment on the tax bill pursuant to Section 25845 of the Government Code.

It is in your financial interest to correct the violations as soon as possible. Any further information may be obtained by contacting the undersigned.

BRL

Bruce De Laura
Building Engineering Inspector Aid
626-574-0941

Date Posted 3/03/09 By *BRL*





DEPARTMENT OF PUBLIC WORKS
BUILDING AND SAFETY DIVISION
REHABILITATION SECTION
900 South Fremont Avenue
Alhambra, CA 91803
(626) 458-3193

JOB ADDRESS: 2366 GLENROSE
ACT.

THIS PROPERTY IS BEING INVESTIGATED
TO DETERMINE SUBSTANDARD CONDITIONS.
UNTIL A COPY OF OUR LETTER TO THE
OWNER IS ATTACHED TO THIS CARD,
DO NOT ISSUE ANY PERMITS
(EXCEPT FOR DEMOLITION) WITHOUT
FIRST CHECKING WITH THE UNDERSIGNED.

DATE: 3/03/09

INSPECTOR: BRD